

Fax Transmission

RECEIVED
CENTRAL FAX CENTER

MAY 31 2005

Date 5/31/05 Time: 3:40Attention to: Mr. X Mrs. Jo Johnson (SILE)Send to: Lanna MaiFax: (703)872-9306 # of pages with cover: 5Document being transmitted: Here is the proper formatfor the amended claim that you require.Additional Information: Thank you for your time and
patience. If you have any questions please feel
free to contact me.Sender: Edgar ChiquinTitle: Patent Application

BEST AVAILABLE COPY



UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE
United States Patent and Trademark Office
Address: COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandria, Virginia 22313-1450
www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
10/623,404	07/21/2003	Edgar Vicente Chiquin		1067
7590	05/23/2005		EXAMINER	
Edgar Chiquin 800 Polo Club Dr. Austin, TX 78737			HANSEN, JAMES ORVILLE	
			ART UNIT	PAPER NUMBER
				3637

DATE MAILED: 05/23/2005

Please find below and/or attached an Office communication concerning this application or proceeding.



UNITED STATES PATENT AND TRADEMARK OFFICE

10/02 3404
 COMMISSIONER FOR PATENTS
 UNITED STATES PATENT AND TRADEMARK OFFICE
 P.O. Box 1450
 ALEXANDRIA, VA 22313-1450
 www.uspto.gov

**Failure to Acceptably Respond to
 Notice of Non-Compliant Amendment (37 CFR 1.121)
 No New Time Period for Reply is Provided**

The amendment document filed on 5/11/05 fails to provide the corrective action required by the prior Notice of Non-Compliant Amendment (37 CFR 1.121) mailed on 5/2/05. The amendment, including both the originally filed amendment and the amendment filed in response to the prior notice, is still considered to be non-compliant under 37 CFR 1.121. In order for the amendment document to be compliant, correction of the item(s) listed below is required. Only the corrected section of the non-compliant amendment document must be resubmitted (in its entirety), e.g., the entire "Amendments to the claims" section of applicant's amendment document must be re-submitted. 37 CFR 1.121(h).

The period for reply continues to run from the mailing date of the prior Notice of Non-Compliant Amendment. The corrections listed below must be timely filed to avoid abandonment of the application. No new time period for reply is provided in this communication. See the Manual of Patent Examining Procedure (MPEP) § 714.03.

If the period for reply set forth in the prior Notice of Non-Compliant Amendment has expired, this application will become abandoned unless applicant: (1) corrects the deficiency, and (2) obtains an extension of time under 37 CFR 1.136(a). In no case may an applicant reply outside the SIX (6) MONTH statutory period or obtain an extension for more than FIVE (5) MONTHS beyond the date for reply set forth in the prior Notice of Non-Compliant Amendment (37 CFR 1.121).

THE FOLLOWING CHECKED (X) ITEM(S) CAUSE THE AMENDMENT DOCUMENT TO BE NON-COMPLIANT:

- 1. Amendments to the specification:
 - A. Amended paragraph(s) do not include markings.
 - B. New paragraph(s) should not be underlined.
 - C. Other _____
- 2. Abstract:
 - A. Not presented on a separate sheet. 37 CFR 1.72.
 - B. Other _____
- 3. Amendments to the drawings: _____
- 4. Amendments to the claims:
 - A. A complete listing of all of the claims is not present.
 - B. The listing of claims does not include the text of all pending claims (including withdrawn claims)
 - C. Each claim has not been provided with the proper status identifier, and as such, the individual status of each claim cannot be identified. Note: the status of every claim must be indicated after its claim number by using one of the following 7 status identifiers: (Original), (Currently amended), (Canceled), (Withdrawn), (Previously presented), (New) and (Not entered).
 - D. The claims of this amendment paper have not been presented in ascending numerical order.
 - E. Other See website below for further explanation or any document.

For further explanation of the amendment format required by 37 CFR 1.121, see MPEP § 714 and the USPTO website at <http://www.uspto.gov/web/offices/pac/dapp/opla/procnotice/officelifevr.pdf>.

Jon Johnson
 Supervisor Legal Instruments Examiner (SLIE)

571-272-6101
 Telephone No. 1.7

Listing of Claims:**Claim 1 (Currently amended)**

[1. An entertainment movie unit inside a restaurant for viewing movies, the entertainment movie unit comprising:]

In combination a booth, portable DVD player and slid able wooden tray comprising: a slide able and a portable DVD player positioned underneath the surface of a [table] [or] booth thereof; [a wooden tray means having a surface for supporting the portable DVD player;]

[means coupling the tray means and the housing for slide-out movement of the wooden tray means through the underneath of the table or booth to a sliding in and out position wherein the portable DVD player is outside the table or booth and accessible for opening and viewing purposes, and to a closed position wherein the wooden tray is located underneath the table or booth for storage;]

wherein the portable DVD player is accessible by sliding out the said wooden tray from said underneath surface of a booth for viewing purposes while in an open position, and is stored underneath the said surface of a booth by sliding in the said wooden tray from said underneath surface of a booth wherein the portable DVD player is stored in a closed position; in which slid able wooden tray is permanently fixed underneath surface of a booth by two wooden side supports with a relatively strong wood adhesive means.

for filing
Reply TO O.A.
Filed on May 23, 2005

[an anti-theft wire connected to the wooden tray means; the anti-theft wire having one link on the portable DVD player and the other link on the underneath of the table with a strong adhesive, the link on the portable DVD player cooperating with the housing to slide the wooden tray from underneath table or booth when the tray means is in its slide-out position when the portable DVD player is pivoted to a generally vertically orientation; and]

[means for supporting the tray so that the front of the wooden tray is in generally horizontal orientation while the tray is in its slide-in position, the front face of the wooden tray being relative to the lip of the side said surface from the table or booth means, in a vertical position two side supports fixed to the underneath of the said table or booth with a relatively strong wood adhesive means, and providing support for the wooden tray to slide in and out from underneath the said table or booth and remain in a rested position with the portable DVD player is on its surface mostly always connected for power on a multi AC outlet power tap with other portable DVD players inside the restaurant.]

Claims 2-8 (canceled).

U.S. Pat.
Reply To O.A.
Filed on May 23, 2005

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER: _____**

**IMAGES ARE BEST AVAILABLE COPY.
As rescanning these documents will not correct the image
problems checked, please do not report these problems to
the IFW Image Problem Mailbox.**